

Oil Field Environmental Incident Summary

Incident: 20151101141659 **Date/Time of Notice:** 11/01/2015 14:16

Responsible Party: Meadowlark Midstream Company, LLC

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 10/31/2015 **Time Incident:** 14:30

Facility ID Number:

County: WILLIAMS

Twp: 157 **Rng:** 102 **Sec:** 30 **Qtr:**

Location Description: A line strike occurred along the pipeline right-of-way. The coordinates of the line strike are 48.399962, -103.914921.

Submitted By: Andrew Parisi

Received By:

Contact Person: Andrew Parisi
5831 123rd Drive NW
Epping, ND 58843

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	45	Barrels				
Other						

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No impact or potential to impact surface waters. No threat to the public.

Areal Extent:

When the contractor struck the line, the majority of the produced water within the excavation pit.

Potential Environmental Impacts:

The spill impacted the soil on location. The impacted soil will be excavated and removed from the location. No impact or potential to impact any surface waters.

Action Taken or Planned:

Summit Operations Communications Center shut down the pipeline segment after being notified of the line strike. The saltwater pumps skids were then locked out and tagged out. Vac trucks were immediately dispatched to recover any standing water from the excavation trench and berm area. Remediation crews will begin excavating the impacted soils today (11/01/2015), and recovering any remaining liquids from the trench.

Wastes Disposal Location: Recovered waste and impacted soil will be hauled to a licensed disposal facility in the area.

Agencies Involved:**Updates**

Date: 11/2/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Followup is required.

Date: 12/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 10:55 a.m. The weather was sunny, 19°F, with wind from the west 0-5 mph. There has been a new pipeline installed through a stubble field on the east side of the section. The pipeline that was struck is located in the northeast quarter (middle of field). The area has been regraded. No drainages are marked near the area of the pipeline. Will request confirmation samples to verify cleanup.

Date: 12/2/2015 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Revisited the site because I was in the area. The previous entries still describe the current site. Contact will be made with Meadowlark Midstream to collect more information on this release.

Date: 12/3/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested any documentation the company has about the site.

Date: 12/4/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received information on the site regarding sample results and how the spill was cleaned up.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 2:02 p.m. Weather was snowing with wind out of the west at 35 mph and a temperature of 32 degrees F. The area of impact was a wheat field where the crop had been harvested. No indication on the surface that anything has happened since the crop was put in this past 2016 spring. Throughout the field, volunteer wheat was starting to grow. No signs of stressed vegetation nor bare spots could be found in the field. No additional follow-up needed if lab results come back within compliance range.